
Sheet 1 of 9
Appl. No. 09/459,995; Filed: Dec 14, 1999
Dkt No. 833.00; Group Unit: 2123
Inventors: CHALFIN et al.
Tel. No.: 202-371-2600
For: Synchronization Of Hardware Simulation Processes
REPLACEMENT SHEET






Sheet 2 of 9 Appl. No. 09/459,995; Filed: Dec 14, 1999 Dkt No. 833.00; Group Unit: 2123 Inventors: CHALFIN et al. Tel. No.: 202-371-2600

For: Synchronization Of Hardware Simulation Processes REPLACEMENT SHEET






Sheet 3 of 9 Appl. No. 09/459,995; Filed: Dec 14, 1999 Dkt No. 833.00; Group Unit: 2123 Inventors: CHALFIN et al.

Tel. No.: 202-371-2600 For: Synchronization Of Hardware Simulation Processes REPLACEMENT SHEET








FIG.4

Sheet 5 of 9 Appl. No. 09/459,995; Filed: Dec 14, 1999 Dkt No. 833.00; Group Unit: 2123 Inventors: CHALFIN et al. Tel. No.: 202-371-2600

For: Synchronization Of Hardware Simulation Processes







FIG.5


Sheet 6 of 9
Appl. No. 09/459,995; Filed: Dec 14, 1999
Dkt No. 833.00; Group Unit: 2123
Inventors: CHALFIN et al.
Tel. No.: 202-371-2600
For: Synchronization Of Hardware Simulation Processes
REPLACEMENT SHEET





Sheet 7 of 9
Appl. No. 09/459,995; Filed: Dec 14, 1999
Dkt No. 833.00; Group Unit: 2123
Inventors: CHALFIN et al.
Tel. No.: 202-371-2600
For: Synchronization Of Hardware Simulation Processes





Sheet 8 of 9 Appl. No. 09/459,995; Filed: Dec 14, 1999 Dkt No. 833.00; Group Unit: 2123 Inventors: CHALFIN et al.

Tel. No.: 202-371-2600

For: Synchronization Of Hardware Simulation Processes






FIG.8

Sheet 9 of 9
Appl. No. 09/459,995; Filed: Dec 14, 1999
Dkt No. 833.00; Group Unit: 2123
Inventors: CHALFIN et al.
Tel. No.: 202-371-2600
For: Synchronization Of Hardware Simulation Processes






FIG.9